FITNESS CERTIFICATE 1) Name of School : Isabella De Rosis Public School 2) Name of Officer : ARUN.M 3) Location : Chirakkakam (Thevarkad), Aluva - Educational Sub District 4) Period of which the certificate is issued : 2024-2025 Academic year 5) Types of building Two Storeyed Building Ground Floor $7 \times 6.00 \times 6.00 \times 3.40 \text{ m}$:- RCC Roof :- 7 Class Rooms 1 x 9.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Chemistry Lab 1 x 9.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Composite Lab $1 \times 6.00 \times 6.00 \times 3.40 \text{ m}$:- RCC Roof :- 1 Staff Room First Floor $10 \times 6.00 \times 6.00 \times 3.40 \text{ m}$:- RCC Roof :- 10 Class Rooms 1 x 6.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Digital Class **Ground Floor** 4 x 8.00 x 6.00 x 3.40 m :- RCC Roof :- 4 Class Rooms 1 x 8.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Staff Room 1 x 3.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Principal Room 1 x 8.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Office Room First Floor $5 \times 8.00 \times 6.00 \times 3.40 \text{ m}$:- RCC Roof :- 5 Class Rooms 1 x 8.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Digital Class 1 x 3.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Counselling Second Floor 5 x 8.00 x 6.00 x 3.40 m :- RCC Roof :- 5 Class Rooms 1 x 8.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Maths Lab 1 x 3.00 x 6.00 x 3.40 m :- RCC Roof :- 1 Activity 6) Nature of defect if any a) Foundation land basement b) Superstructure c) Doors and windows d) Wood work wrought and putup Nil e) Roof f) Flooring g) Miscellaneous

7) Any major defects noice which will render the building unsafe in any manner-

No

8) Whether maintenance works have been done properly:

Yes

9) Whether the structure is sound for conducting classes:

Yes, the structure is sound for conducting classes under normal weather conditions.

Note: 1.The stability of the structure should be examined also with reference to the altitude, intensity of wind exposure to flood etc.

2. Any additional observation if deemed necessary for the certificate may be furnished seperately with the certificate.

Certified that the school was inspected by on 17.05.2024 and found to be fit to conduct classes under normal weather conditions.

Place: Varapuzha Date: 17.05.2024



ASSISTATET EN Section
ASSISTATE EN Section
LID & EN Section
Panchayes
Varapuzha Grama Panchayes
Varapuzha P. O., Pin. 683 517